

# Robin Enterprises Co.

*Creative Printing*

Fraction	Decimal	MM
1/64	0.0156	0.0396
1/32	0.0312	0.793
3/64	0.0468	1.19
1/16	0.0625	1.587
5/64	0.0781	1.984
3/32	0.0937	2.381
7/64	0.1093	2.778
1/8	0.125	3.175
9/64	0.1406	3.571
5/32	0.1562	3.968
11/64	0.178	4.365
3/16	0.1875	4.762
13/64	0.2031	5.159
7/32	0.2187	5.556
15/64	0.2343	5.953
1/4	0.25	6.35
17/64	0.2656	6.746
9/32	0.2812	7.143
19/64	0.2968	7.54
5/16	0.3125	7.937
21/64	0.3281	8.334
11/32	0.3437	8.731
23/64	0.3593	9.128
3/8	0.375	9.525
25/64	0.3906	9.921
13/32	0.4062	10.318
27/64	0.4218	10.715
7/16	0.4375	11.112
29/64	0.4531	11.509
15/32	0.4687	11.906
31/64	0.4843	12.303
1/2	0.5	12.7

Fraction	Decimal	MM
33/32	0.5156	13.096
17/64	0.5312	13.493
35/64	0.5468	13.89
9/16	0.5625	14.287
37/64	0.5781	14.684
19/32	0.5937	15.081
39/64	0.6093	15.478
5/8	0.625	15.875
41/64	0.6406	16.271
21/32	0.6562	16.668
43/64	0.6718	17.065
11/16	0.6875	17.462
45/64	0.7031	17.859
23/32	0.7187	18.256
47/64	0.7343	18.653
3/4	0.75	19.05
49/64	0.7656	19.446
25/32	0.7812	19.843
51/64	0.7968	20.24
13/16	0.8125	20.637
53/64	0.8281	21.034
27/32	0.8437	21.431
55/64	0.8593	21.828
7/8	0.875	22.225
57/64	0.8906	22.621
29/32	0.9062	23.018
59/64	0.9218	23.415
15/16	0.9375	23.812
61/64	0.9531	24.209
31/32	0.9687	24.606
63/64	0.9843	25.003
1	1	25.4

To convert MM to Inches: MM divide by 25.4 = inch

To convert Inches to MM: Inch x 25.4 = MM